



# PRESIDENCY UNIVERSITY, BENGALURU SCHOOL OF ENGINEERING

Weightage: 20 %

Max Marks: 40

Max Time: 1 hr.

Monday, 24th September, 2018

TEST - 1

Odd Semester 2018-19

Course: MEC 211 Metrology & Mechanical Measurements.

V Sem. Mechanical

### Instruction:

- Read the question properly and answer accordingly. (i)
- Question paper consists of 3 parts. (ii)
- Scientific and Non-programmable calculators are permitted. (iii)

# Part A

 $(3 Q \times 4 M = 12 Marks)$ 

- 1. A selection of slip gauges is required to build a height of 58.155 mm using two protection gauges of 1.5 mm thickness. Select the best combination of gauges using 112 set.
- 2. Define the following
  - a). Sensitivity b). Calibration
- c). Magnification d). Resolution
- 3. Distinguish between unilateral and bilateral tolerances with a neat sketch.

#### Part B

(3 Q x 6 M = 18 Marks)

- **4.** Discuss the different reasons for the occurrence of systematic/controllable errors.
- **5.** Explain International Prototype Meter with a neat sketch.
- 6. Explain Primary, Secondary and Working Standards.

# Part C

 $(1Q \times 10 M = 10 Marks)$ 

7. Describe the procedure to transfer from Line standard to End Standard.



# PRESIDENCY UNIVERSITY, BENGALURU

# **SCHOOL OF ENGINEERING**

# TEST 2

Odd Semester: 2018-19

Course Code: MEC 211

Course Name: Metrology and Mechanical Measurements

Branch & Sem: MEC & V Sem

Date: 27 November 2018

Time: 1 Hour

Max Marks: 40.

Weightage: 20%

# Instructions:

(i) Read the question properly and answer accordingly.

(ii) Question paper consists of 3 parts.

(iii) Scientific and Non-programmable calculators are permitted.

### Part A

Answer all the Questions. Each question carries four marks.

(3x4=12)

- 1. Differentiate Hole basis system and Shaft basis system.
- 2. What is maximum material limit? Explain w.r.t. hole and shaft.
- 3. Derive an expression for Best size wire to measure effective diameter of screw thread.

# Part B

Answer all the Questions. Each question carries eight marks.

(2x8=16)

- 4. With neat diagram explain Gear tooth terminology (at least five important parameters).
- 5. Derive an expression for Three wire method to determine effective diameter of screw thread.

## Part C

Answer the Question, Question carries twelve marks.

(1x12=12)

6. Determine the actual dimensions to be provided for a shaft and hole 90 mm size for **H8e9** type clearance fit. Size 90 mm falls in the diameter step of 80 - 100 mm. Value of standard tolerance unit  $i=0.45\sqrt[3]{D}+0.001D$ . The values of tolerances for IT8 & IT9 grades are 25i & 40i respectively. Value of fundamental deviation for 'e' type shaft is -11D<sup>0.41</sup>. Also design the GO & NO GO gauges considering wear allowance as 10% of gauge tolerance.



Roll No.							
----------	--	--	--	--	--	--	--

# PRESIDENCY UNIVERSITY BENGALURU

# **SCHOOL OF ENGINEERING**

# **END TERM FINAL EXAMINATION**

Odd Semester: 2018-19

Date: 28 December 2018

Course Code: MEC 211

Time: 2 Hours

**Course Name**: Metrology and Mechanical Measurements

Max Marks: 80

Programme & Sem: MECH & V Sem

Weightage: 40%

# Instructions:

(i) Read the question properly and answer accordingly.

- (ii) Question paper consists of 3 parts.
- (iii) Scientific and Non-programmable calculators are permitted.

# Part A

Answer all the Questions. Each question carries five marks.

(4Qx5M=20)

- 1. Define measurement. Mention types of measurement.
- 2. What is a Transducer? Explain passive transducer.
- 3. Write note on Thermistors.
- 4. Explain the procedure for bonding of strain gauges.

# Part B

Answer **all** the Questions. **Each** question carries **eight** marks.

(5Qx8M=40)

- 5. Sketch and explain Generalized measurement system with suitable example.
- 6. With neat diagram explain Equal arm balance. Derive an equation for sensitivity for the same.
- 7. Explain Hydraulic dynamometer with neat diagram. List any four advantages of the same.
- 8. With neat sketch explain working of proving ring.
- 9. With neat sketch explain any one device/instrument to measure flow rate.

#### Part C

Answer **both** the Questions. **Each** question carries **ten** marks.

(2Qx10M=20)

- 10. With neat diagram explain optical pyrometer.
- 11. Explain McLeod Gauge (derivation of expression for pressure should be included)

